

ASSIST™ Software 3.2R4 Release Notes

System Requirements

- Supported operating systems: Windows 8, Windows 8.1, and Windows 10 (32-bit and 64-bit editions)
- Processor: Core i3 or better (or equivalent)
- Memory: 4 GB or more (recommended: 8 GB)
- Minimum available disk space: 80 GB
- Recommended network: Built-in network card (USB-to-network adapter also acceptable)
- Display: 13" or larger (recommended: 15")
- Minimum resolution: 1024 × 768 pixels

Firmware

- Included in this release of ASSIST is the following firmware:
 - 1.0R9 for AMIGO™ 2
 - 1.0R5 for U41™
 - 1.0R5 for EDDYFI TECHNOLOGIES TOPSIDE UNIT™

New Features and Improvements

- Over-the-air Updater (OTA Updater): New software versions are available to install through a Wi-Fi connection.

Modifications to Existing Features

None in this version

Dropped Features

None in this version

Resolved Issues

- Software installer failure related to setup of prerequisite files with some computers running on Windows 10.
- Windows 7 incompatibility: The new software installer will not allow installation on Windows 7.

Known Issues, Limitations, and Restrictions

- Installing Assist while probes are connected may cause installation failures.
- Changing notes or regions in components and pages recorded using versions prior to Assist. 3.2R3 will render those notes and regions unavailable when trying to read back using prior versions of Assist.

- Scrolling the page list using the thumb-scroll method works intermittently.
- Regions and defects are not visible during replay.
- Cannot export a landscape-oriented report to pdf.