



Lyft™ Software 1.1R7 Release Notes

System Requirements

- Lyft instrument
- Electronics upgrades are necessary to fully support the new features of the version:
 - The PEC pulser/receiver board should be revision D or later
 - The PEC side plate board should be revision E or later

New Features and Improvements

- Improved immunity to noisy environments

Modifications to Existing Features

None

Dropped Features

None

Resolved Issues

Note

Known Issues, Limitations, and Restrictions

None notable in this version.