

M2M CAPTURE SOFTWARE VERSION 3.4.1

HOTFIX INFORMATION

License management is changing between Capture v3.3 and Capture v3.4. An Internet connection is required to complete the first update from 3.3.X or former.

Please check the date, the hour and the time zone on the instrument before updating.

Main fixes and optimizations between Capture v3.4 and Capture v3.4.1

- Licensing issues due to incoherence in time zone
- P button on the instrument front panel now functional to call the RMS software
- Synchronized TCG applied
- Bright pixels on the median line of TFM pictures removed
- Filters and averaging live activated (PA and conventional UT)
- Black lines on C-scan along the scan axis (corrosion mapping)
- Mantis: New battery life management to avoid unexpected shut down. The internal temperature info is not displayed. The % of the remaining battery life is averaged between the internal battery level and the removable battery level.
- Diverse instabilities

Known issues

- Artefacts on TFM pictures for high gain
- Display of the TCG curve not synchronized.

For any questions, remarks or support needs, please contact us at support@eddyfi.com