

M2M PANTHER – ACQUIRE 1.2.3

HOTFIX INFORMATION

Main fixes between Acquire v1.2.0 and Acquire v1.2.3

- Inactive channels with Panther64:64PR when using TFM/ATFM wizards
- Acquire launch blocked with Panther256:256
- Corrections in the API M2M_9.2

Remaining issues

- Field calculation not functional through the CIVA configuration panel
- Probe offsets and probe orientation not applied correctly unless the Init button) is clicked
- Weld overlay not properly displayed on T-Scan with cylindrical configurations

For any questions, remarks or support needs, please contact us at support-m2m@eddyfi.com