

Eddyfi Robotics Inc. 2569 Kenworth Road, Suite C Nanaimo, BC, V9T 3M4 CANADA

+1.250.729.8080 info@eddyfitechnologies.com www.eddyfitechnologies.com

# ICON TROUBLESHOOTING GUIDE



# TABLE OF CONTENTS

Template

11 Mar 2018

0062

Revision

B03

Document

UMCF017392

 $c: \verb|\c| c: \verb|\c| c$ 

Installation
A Mandatory Prerequisite Was Not Installed3
Symptom(s)3
Cause(s)3
Resolution3
Clean Installation4
Symptom(s)4
Cause(s)4
Resolution4
Video4
Blackmagic Does Not Appear In ICON4
Symptom(s)4
Cause(s)4
Resolution4
Blank Video Preview5
Symptom(s)5
Cause(s)5
Resolution5
No Video Signal7
Symptom(s)7
Cause(s)7
Resolution
Communication9
No Serial Ports Found9
Symptom(s)9
Cause(s)9
RESOLUTION(S)9

Revision

A03

Date

10 Dec 2020

Author

CG

IPN

3092392-A03

Page 1 of 11



Serial Device(S) Not Found	c
Symptom(S)	9
Cause(S)	g
REsolution(S)	9
Job Issues	
Can't Start Job	10
Symptom(S)	10
Cause(S)	10
Resolution(S)	10

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date		Source Location				
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 2 of 11




# INSTALLATION

#### A MANDATORY PREREQUISITE WAS NOT INSTALLED

### SYMPTOM(S)


During the installation process of ICON the following error message appears



# CAUSE(S)

- Computer needs to be restarted
- Windows updates need to be installed
- User is not an administrator
- System is not running Windows 10
- Conflict with installed version of Microsoft SQL Server Data-Tier Application
- Firewall/Anti-virus
- SQL Server Attempted to perform an unauthorized operation (Windows 10 20H2)

#### **RESOLUTION**



Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date	Date Source Location					
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 3 of 11



Follow Microsoft article KB4594205 for Attempt to perform an unauthorized operation (Windows 10 20H2) <a href="https://support.microsoft.com/en-ca/help/4594205/kb4594205-setup-or-patching-sql-server-instances-fail-with-error-attem">https://support.microsoft.com/en-ca/help/4594205/kb4594205-setup-or-patching-sql-server-instances-fail-with-error-attem</a>

8.

#### **CLEAN INSTALLATION**

#### SYMPTOM(S)

Sometimes it may become necessary to perform a clean installation if ICON because of upgrades or failed installations.

#### CAUSE(S)

- Major Upgrade
- Failed Installation

#### **RESOLUTION**

- 1. Uninstall the following Items from Apps & Features
  - a. ICON
  - b. SQL Server 2016 (ICONSUITE4 Instance)
  - c. Microsoft SQL Server Data-Tier Application Framework (x86 and x64)
  - d. Microsoft XNA Framework Redistributable 4.0 Refresh
  - e. Medialooks MPlatform SDK
- 2. Remove the Medialooks folder from C:\Program Files (x86) if found
- 3. Remove ICON 4 folder from C:\ProgramData (Folder is hidden by default)
- 4. Remove ICON folder from C:\ProgramFiles if found

# VIDEO

## BLACKMAGIC DOES NOT APPEAR IN ICON

#### SYMPTOM(S)

Blackmagic capture devices do not appear as selection options in the Grabber Device dropdown menu

# CAUSE(S)

- Blackmagic device drivers not installed
- Correct Blackmagic driver version installed
- Upgraded ICON version

# **RESOLUTION**

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date		Source Location				
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 4 of 11



- 1. Check Blackmagic is installed.
  - a. Apps & Features: Blackmagic Desktop Video (Should be in the Apps & Features list)
  - b. Device Manager: No Unknown devices. Should show up under Sound, video and game controllers
    - ¶ Sound, video and game controllers
      - Blackmagic DeckLink Studio 4K
      - Blackmagic DeckLink Studio 4K Audio
      - Blackmagic DeckLink Studio 4K AVStream
- 2. Check Installed Blackmagic version (Version 11.6 or greater required as of November 16, 2020)



- a. If version is less than 11.6.x (ie. 10.8.6). Upgrade to the latest version available from blackmagicdesign.com
- 3. If still not resolved Uninstall Blackmagic Desktop Video from Apps & Features. Reinstall with latest version available from blackmagicdesign.com

#### **BLANK VIDEO PREVIEW**

# SYMPTOM(S)

• Blank screen appears where video should be displayed in ICON.

# CAUSE(S)

- A monitor was added or removed
- Windows was locked
- Alt-Ctrl-Delete was used to lock the system or launch Task Manager

#### **RESOLUTION**

Close ICON and relaunch the application.

• This only affects Preview, not capture.

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date Source Location						
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 5 of 11



• All these functions cause a change to how windows drive the display. This requires a refresh to the Direct X device managed by our Video API Vendor (Medialooks) to reset. This was turned off on purpose to avoid the preview from flickering on systems without powerful graphics.

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date		Source Location				
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 6 of 11



# NO VIDEO SIGNAL

#### SYMPTOM(S)

• Launching ICON results in a "No video Signal" screen being shown.



# CAUSE(S)


- Grabber Device configuration incorrect
- Power issues with camera/system and top end interface
- Video cable(s) have become loose or disconnected
- Video Grabber device driver issue
- Video signal issue

# **RESOLUTION**

- Check that the Grabber device has been configured correctly. Refer to the ICON user manual for how to adjust the grabber settings. Refer to the camera/system/interface manuals to find the correct video format.
- 2. Ensure the camera and interface have power and are plugged in and turned on.
- 3. Check video cables from interface to grabber. Make sure they are plugged in correctly. Unplug and plug them back in to make sure they are connected properly. Check interface manual to make sure cable is plugged into the correct video output jack.
- 4. Grabber device driver issue. The Blackmagic driver has been observed to not switch the input line on the grabber. The resolution is as follows.
  - a. Open Blackmagic Desktop Video Setup
  - b. Select grabber and open settings

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date	Source Location					
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 7 of 11





c. Select the Video Input tab. Select the correct input connection to be used (Example. Component). Click Save.



- d. Repeat steps b and c for each Blackmagic grabber installed.
- 5. If there is a suspicion of a video signal issue (Distorted image, flickering, no signal) after all previous steps have been attempted. Contact Eddyfi Robotics Service and Support.

Templa	te Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date		Source Location				
11 Mar	2018	c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.	docm			Page 8 of 11



# COMMUNICATION

#### NO SERIAL PORTS FOUND

#### SYMPTOM(S)

• The serial port(s) for my system do not appear in the drop-down menu in ICON

# CAUSE(S)

- USB to serial converter cable is unplugged or damaged
- Interface box is unplugged or turned off
- USB to serial converter driver is not installed

## RESOLUTION(S)

- 1. Inspect USB cable used for communications for PC to Interface box for damage (kinks, cuts, etc..). Replace if damage is found or cable is missing
- 2. Unplug the cable at both ends and plug back in to make sure cable is plugged in and seated properly
- 3. Ensure the interface box is plugged in and powered on
- 4. Install the latest FTDI Chip Serial driver from website, https://www.ftdichip.com/Drivers/D2XX.htm
- 5. If problem persists, uninstall, and reinstall serial port drivers

## SERIAL DEVICE(S) NOT FOUND

#### SYMPTOM(S)

- During system initialization in ICON a Device Connection Error occurs
- Device fails discovery in ICON Diagnostics

# CAUSE(S)

- Device(s) are unplugged or powered off
- Device Serial number and or Node ID conflict
- Device Serial number entered incorrect

# RESOLUTION(S)

- 1. Ensure device is plugged in properly and is powered on.
- 2. Inspect cabling for damage (kinks, cuts, etc.)
- 3. Using ICON Diagnostics, Scan for Devices. Does the device appear?
  - If the device does appear do the following
    - i. Hook up the device separately and use Broadcast function
    - ii. If the device appears verify the serial number is correct. If not update the serial number.
  - If the device does not appear. Contact Service.
- 4. Verify the device serial number is correct in the loaded ICON configuration

Template	Revision	Document	Revision	Date	Author	IPN
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03
Date		Source Location				
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 9 of 11



5. In ICON Diagnostics scan the system. If device(s) do not appear scan using their serial number. If they appear verify there are no duplicate node id's or serial numbers. If there are resolve the conflicts by changing the necessary serial number(s) or node id's with ICON Diagnostics


Contact Service if problem persists.

# JOB ISSUES

#### CAN'T START JOB

# SYMPTOM(S)

Upon starting a job an error message appears with the following details.




#### CAUSE(S)

• User does not have permissions to access the recording folder

# RESOLUTION(S)

1. Add Full Control Permissions to the C:\ProgramData\ICON 4 folder to all Users.



Template	Revision	Document	Revision	Date	Author	IPN	
0062	B03	UMCF017392	A03	10 Dec 2020	CG	3092392-A03	
Date		Source Location					
11 Mar 2018		c:\epdm\isleng\products\cf-inuktungui\manuals\umcf017392.docm				Page 10 of 11	