

M2M CAPTURE SOFTWARE VERSION 3.4.2

HOTFIX INFORMATION

License management is changing between Capture v3.3 and Capture v3.4. An Internet connection is required to complete the first update from 3.3.X or former.

Main fixes and optimizations between Capture v3.4.1 and Capture v3.4.2

- Random black lines missed on the C-scan during inspection in raster scan
- Maximal TFM aperture display on Gekko package
- DXF import optimization (both as overlay and as part)
- Probes display on the analysis 3D view
- Various instabilities

Known issues

- Display of the TCG curve not synchronized

For any questions, remarks or support needs, please contact us at support@eddyfi.com